

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11399

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080036-4

RECEIVED FROM

PLANT #9

DATE REC'D. 27-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO  
QUANTITY  
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. CR W.O. NO.	S.O. NO.	REMARKS
DRAWING NO. AND DESCRIPTION							QUANTITY	ACCEPTED	REJECTED	
105	322	254	0 20				105			

IPS #4003323

*H.C. Parker*  
*3/26/57*  
*H.C. Parker*RECEIVED  
BYINSPECTED  
BY

DATE

REJECTS RETURNED  
ON SHIP. MEMO NO.

RECEIVED FROM

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11415

CHARGE TO  
QUANTITY  
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. CR W.O. NO.	S.O. NO.	REMARKS
DRAWING NO. AND DESCRIPTION							QUANTITY	ACCEPTED	REJECTED	
30	322	NOTL	20	0 10			10			

To supersede RIR #11345

IPS #4003397

*H.C. Parker*  
*3/26/57*  
*H.C. Parker*RECEIVED  
BY

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080036-4